

## 13.16.320 Abandonment of water wells required

---

### **13.16.320 – Abandonment of water wells required**

No water from the city water supply shall be turned on for service into any premises which have been tapped on to the city water mains, unless and until any and all existing water wells located on the premises being served shall have been abandoned and plugged in accordance with the requirements of Chapter 96 1/2, Paragraphs 5422 and 5425 of the Illinois Revised Statutes (1987 Ed) and such rules as are promulgated thereunder and applicable rules adopted for plugging and abandonment requirements which are more stringent than the rules of the Department of Mines and Minerals where such rules have been adopted by the Illinois Pollution Control Board.

(1988-M-32 : § 1)